Audio	Quick Service Manual	Ref.No. : MESA0303PM17a
		Date : 31.March. 2004(Revised)
	Model : SA-PM17,PM27,PM47	Cases reported (country)
		Japan

Special customer inquiry ☐	Parts shortage solution ☐	Frequnce	level
Improve by External factor ☐	Product improvement ■	High (Low) A few	One

Subject : **CD Tray does not open/Close (CR16 Mechanism)**

Symptom : Tray does not open/Close, Tray stuck

Cause : 1) Misalignment of mechanism.
2) Shift UD SPEED DOWN GEAR by abnormal use.
when Tray was jammed with Mechanism chassis Ribs
3) No complete initialization at power off mode.

Remedy : 1) Add Screw to secure Gear in place. (Part No: XTBS26+8J)

do not overtighen SCREW.

2) **Replace Select Drive Gear**(RDG0537)

3) Cut the Ribs on the right side of the Mecahanism Base

Cut all RIBS

File down surface to prevent mechanical noise.

4) Complete Alignment

Utility knife

Note) Do not pull out the AC cord until the "GOOD BYE" message disappears.

Action on production :

1) From end of Nov. 2002mechanism production onwards.

Suffix was changed to "**C**" 440* - C

Indication is on Machanism base

2)Rib cut is not adopted to MP, because this model was discontinured.