

Product :	DVD	Bulletin No. :	07-DVD-E03
Model :	DVD-R150/XAZ,DVD-R155/XAZ	Bulletin Date :	29-May-07
Buyer :	SEDA	ECN Date :	AK020070310
SUBJECT : INFORMATION OF ACS(Auto Clock Setting) problem			

Background : ► This is INFORMATION OF ACS(Auto Clock Setting) problem

Note : ► Symptom : Below symptom is occurred every 9 PM

1. If the unit don't have Disc, The loader moves automatically during 5 seconds.
2. If the unit have Disc, The disc rotates during 5 minutes automatically.

► Cause : S/W error

► Solution : Upgrade the unit using firmware.

Application Date :

(Interchangeability Code : * I.C)

Location	OLD (before) Parts			NEW (changed) Parts			*
No.	SEC Code	Description		SEC Code	Description		I.C
H207							
Type	A type	B type	C type	D type	E type	F type	
Interchange Type Code (* I.C)	OLD → Early (Parts) (Prod.) NEW → Late (Parts) (Prod.)	OLD → Early (Parts) (Prod.) NEW → Late (Parts) (Prod.)	OLD → Early (Parts) (Prod.) NEW → Late (Parts) (Prod.)	OLD → Early (Parts) (Prod.) NEW → Late (Parts) (Prod.)	Parts Addition (None → New)	Parts deletion (Old → Del.)	
Application	Reference (O)	Only Defected sets ()	Whole sets ()				
Attachment	Schematic Diagram ()	Component Lay-out ()	Exploded View ()				
	Mechanical Diagram ()	None (●)	Others ()				

Product Month :	Serial No. (~ from) :
Published by :	Checked by :
	Approved by :