


7. Refrigerant Gas Circulation Diagram



(Kinds of welding)

- : 25% silver solder welding
- : 0% silver solder welding
- △ : FLASH BUTT welding
(Al+Cu)
- ◇ : ARGON welding
(Al+Al)