

SAMSUNG

DVD RECEIVER AMP

HT-DS100 N/ DS110 N / DS140 N

(OLD MODEL: HT-DS100/ DS110/ DS140)

* Difference of **DS100 Series** and **DS100N Series**.


1. some parts of Total Exploded View's parts are different.
2. Electrical parts are perfectly different.

SERVICE Manual

SUPPLEMENT-1

For example..

At service repair, Method that distinguish with old DS100 model is same with below picture.




RATING LABEL is stuck of "HT-DS100N" upside REAR CABINET.

In this case, you must use this service manual.

(material number: AH68-01642F)

DVD RECEIVER AMP SYSTEM



CONTENTS

1. Alignment and Adjustments
2. Exploded Views and Parts List
3. Electrical Parts List
4. Block Diagrams
5. Wiring Diagram
6. Schematic Diagrams
7. IC Block Diagrams
8. Troubleshooting

Notice !!

You can search for the updated part code through ITSELF web site.
URL; <http://itself.sec.samsung.co.kr>

- Confidential -



This Service Manual is a property of Samsung Electronics Co.,Ltd.
Any unauthorized use of Manual can be punished under applicable
international and/or domestic law.

© Samsung Electronics Co.,Ltd. OCT. 2004
Printed in Korea
Code no. AH68-01642F